

Near-Miss Reports – Structure Fires with Situational Awareness as a Contributing Factor

Report Number	Report	Report Date	Event Date
<u>13-0000307</u>	Hopper fire explodes during event.	03/12/2013 1649	05/23/2012 1357
<u>12-0000253</u>	Structural collapse occurs during commercial fire.	09/27/2012 1907	09/18/2012 1000
<u>12-0000174</u>	Porch collapses during overhaul.	06/19/2012 2159	06/19/2012 0306
<u>12-0000088</u>	Freelancing puts ladder crew at risk.	03/24/2012 0720	03/13/2012 2327
<u>12-0000036</u>	Crews endangered by lack of communication.	02/14/2012 1732	02/10/2012 0700
<u>11-0000412</u>	FF partially trapped during roof ventilation.	12/28/2011 1449	03/30/1998 0000
<u>11-0000385</u>	FFs avoid falling into pit.	12/06/2011 2007	11/29/2011 1300
<u>11-0000376</u>	Firefighter misjudges distance and falls.	12/01/2011 1057	09/12/2009 0327
<u>11-0000323</u>	Heavy water load collapses chicken house ceiling.	10/17/2011 1435	10/15/2011 1924
<u>11-0000139</u>	Large hole underneath burning shop.	04/08/2011 1403	04/02/2011 0039
<u>11-0000137</u>	Responder nearly ran over stretching line.	04/07/2011 1254	03/01/2011 0030
<u>10-0001257</u>	Flashover and collapse injures firefighter.	12/03/2010 1500	10/02/2010 2100
<u>10-0001250</u>	Safety officer injured in wall collapse.	12/03/2010 1447	01/06/2006 2100
<u>10-0001163</u>	Horizontal ventilation causes explosion.	11/03/2010 1626	07/14/1999 2130
<u>10-0001086</u>	Crew moves to safety just before wall collapse.	09/13/2010 1208	10/31/1987 0000
<u>10-0001029</u>	Assigned engine fails to supply water.	08/05/2010 1251	04/04/2004 0900
<u>10-0000998</u>	Flashover cuts off attack team.	07/24/2010 1419	06/20/1989 1400
<u>10-0000962</u>	Egress becomes an issue for roof crew.	07/13/2010 1121	12/24/2002 1700
<u>10-0000959</u>	Roof collapse leaves FF stranded.	07/13/2010 1005	04/04/1993 1800
<u>10-0000937</u>	Vehicle on hoist falls during fire attack.	07/06/2010 1142	02/01/2008 0500
<u>10-0000910</u>	Hydrants can be hazardous.	07/01/2010 1244	04/01/2006 1200
<u>10-0000825</u>	Attack crew works on weakened floor.	06/10/2010 1005	02/05/2003 2300
<u>10-0000768</u>	Falling AC unit poses threat to FFs.	05/18/2010 1032	05/06/1999 1630
<u>10-0000765</u>	FF on roof steps through skylight.	05/18/2010 1015	08/08/2000 1300
<u>10-0000681</u>	Basement fire flashes when door is opened.	04/04/2010 1216	11/21/2001 1100
<u>10-0000666</u>	HVAC falls through roof.	04/01/2010 1801	01/15/2010 0000
<u>10-0000605</u>	Attack crew falls through burned out floor.	03/27/2010 1128	03/27/2009 1600
<u>10-0000595</u>	Evacuation order saves lives at warehouse on fire.	03/27/2010 1016	09/18/2007 1806
<u>10-0000529</u>	Special hazards noted at commercial fire.	03/24/2010 1118	05/01/2009 1100
<u>10-0000525</u>	Falling AC unit poses hazard to FFs.	03/24/2010 1113	07/01/2006 0700
<u>10-0000516</u>	Evacuation ordered during fire attack.	03/24/2010 1106	01/21/1997 1100
<u>10-0000513</u>	Safety concerns of roof crew not well communicated.	03/24/2010 1013	01/20/1996 0800
<u>10-0000488</u>	Downed wires identified while advancing hose.	03/14/2010 1652	10/19/2008 2100
<u>10-0000478</u>	FF's boot crushed as aerial is retracted.	03/14/2010 1230	12/01/2005 1900
<u>10-0000465</u>	Overhanging roof fails without warning.	03/13/2010 0922	05/14/1994 1000
<u>10-0000422</u>	Lack of lighting causes FF to walk off dock.	03/10/2010 2111	03/10/2005 0200
<u>10-0000418</u>	FF self rescues following roof collapse.	03/10/2010 2018	05/15/1985 1700
<u>10-0000213</u>	Weakened floor fails during search.	02/02/2010 1503	02/02/2009 1300
<u>10-0000190</u>	Light weight truss roof collapses during attack.	01/30/2010 1728	06/07/1989 1400
Report Number	Report	Report Date	Event Date

10-000097	Hand severely injured while breaking glass window.	01/14/2010 0037	01/15/1996 2100
09-0001089	Multiple hazards present as wall collapses.	12/12/2009 2241	03/13/2000 1030
09-0001006	Battalion chief inhales smoke during walk around.	11/17/2009 1056	01/10/2009 0900
09-0000965	Debris falls through ceiling injuring attack crew member.	10/31/2009 1507	05/01/2005 1530
09-0000949	Safe ventilation procedures require training.	10/27/2009 1511	10/17/2009 0748
09-0000902	Multiple safety issues during aerial operations.	10/01/2009 1907	09/29/2009 1630
09-0000901	Ladder operations hindered by lack of communication.	10/01/2009 1351	05/05/1981 1300
09-0000851	FF falls into pit at structure fire.	08/28/2009 0635	01/01/1986 0300
09-0000818	Ventilation operation caused light fixture to fall.	08/24/2009 1203	06/09/2009 2300
09-0000802	Exposure line bursts causing catastrophe.	08/22/2009 0512	06/28/1994 1500
09-0000710	Hidden elevator shaft causes FF to fall during a search.	07/30/2009 1007	07/15/2009 1100
09-0000696	Broke energy line shocks FF.	07/16/2009 1655	07/15/2009 1404
09-0000683	Propane tanks explode and almost hit aerial platform.	07/15/2009 1610	05/21/2007 0030
09-0000680	Falling power lines block egress.	07/15/2009 1127	05/21/2007 2100
09-0000664	Changing fire conditions results in evacuation.	07/09/2009 0808	12/05/2006 1400
09-0000586	Overhead heating unit falls from supports.	06/14/2009 1115	10/04/2002 1000
09-0000578	Collapse of building injures FFs.	06/13/2009 0923	08/14/2008 0930
09-0000564	Fire through the roof causes furnace units to fall.	06/06/2009 1903	01/01/2006 0045
09-0000532	Changing attack mode in structure fire.	05/26/2009 1124	05/12/1999 2300
09-0000527	FF almost falls through hole in floor.	05/24/2009 0750	06/01/1989 1100
09-0000485	Lightweight failure causes firefighter to fall.	05/12/2009 0002	11/26/2006 0600
09-0000444	Poor unity of command at commercial structure fire.	04/27/2009 1734	02/10/2004 0530
09-0000366	FF falls through ice into hidden pit.	04/06/2009 1106	01/05/1996 1400
09-0000312	Pre-planning emphasized in size-up.	03/24/2009 1043	07/15/1994 2100
09-0000293	Unsafe roof operation threaten FFs.	03/15/2009 0608	03/17/1979 0000
09-0000251	Carpet traps firefighters.	03/06/2009 1517	04/10/1987 0455
09-0000226	Conditions change, FFs evacuated.	02/28/2009 2136	05/10/2003 0000
09-0000175	Fall from aerial turntable due to taking 'short cut'.	02/20/2009 0108	02/18/2009 0230
09-0000116	Effective incident command structure pays off .	02/04/2009 1011	10/30/2008 0832
09-0000054	No SCBA check leads to smoke poisoning.	01/18/2009 1943	05/10/2002 1500
09-0000050	FF falls 12' into airshaft.	01/18/2009 1524	12/05/1994 2100
09-0000019	Dropped pike pole misses FF by inches.	01/12/2009 1953	06/01/2000 2200
08-0000665	Firefighter throws ladder into power lines.	12/27/2008 1223	12/24/2008 1600
08-0000661	Burned conveyor belt leads to fall and injury.	12/23/2008 2306	11/29/2008 1730
08-0000656	Energized power lines and aerials do not mix.	12/18/2008 1824	11/13/2008 1409
08-0000545	Hoseline deployment affects pressure.	10/30/2008 0750	10/10/2008 1630
08-0000535	Roof becomes spongy and bows with FFs weight.	10/28/2008 1339	06/23/2008 0000
Report Number	Report	Report Date	Event Date

08-0000468	Awning collapse injures fire fighters.	09/24/2008 1145	12/15/2007 1237
08-0000401	Roof collapse at well involved commercial fire.	08/26/2008 1259	06/05/2008 1230
08-0000399	Radio transmission saves truck crew.	08/23/2008 2044	08/22/2008 0139
08-0000395	Lieutenant falls through roof up to his waist.	08/22/2008 1711	02/20/2007 1330
08-0000335	Uncoordinated fire attack creates dangerous situation.	07/14/2008 1327	07/11/2006 1800
08-0000305	Salvage and overhaul can hurt you.	06/20/2008 0631	06/18/2008 0000
08-0000247	Heart condition discovered at fire alarm.	05/18/2008 2128	02/03/2008 2100
08-0000018	Situational awareness prior to ceiling collapse prevents injuries.	01/10/2008 1830	04/01/2001 1600
07-0001149	Aerial receives damage from electrical arc	12/05/2007 1745	11/27/2007 1630
07-0000875	Established collapses zones save crew.	04/18/2007 1328	11/30/2006 0730
07-0000798	Inexperienced FFs left in warehouse fire, no radios.	03/13/2007 1043	06/12/1974 2300
07-0000780	Improper interior high rise operations.	03/08/2007 1611	03/02/2007 0815
07-0000692	Identified hazard proves to be hazardous.	01/21/2007 1229	01/18/2007 1244
07-0000648	Pumper slides downhill on ice while pumping at structure fire.	01/05/2007 1550	01/01/1997 0030
06-0000297	Commercial/Industrial Fire with Explosion	05/26/2006 1028	12/05/2005 0500
11-0000138	Dust fire engulfs FF during overhaul.	04/07/2011 1310	01/20/2011 0000
10-0000816	HVAC unit falls from roof.	06/09/2010 0737	09/30/2000 0001
09-0000350	FF working on catwalk loses situational awareness.	04/03/2009 1256	11/01/1987 1000
09-0000191	Firefighter falls while descending ladder.	02/22/2009 1038	02/18/2009 1900
08-0000554	Fire Officer burned by grabbing hot flue with ungloved hand.	10/30/2008 2211	09/04/2008 0000
08-0000522	Coal dust ignition endangers overhaul crew.	10/20/2008 1238	10/14/2008 1727
07-0000912	Collapse of wall nearly falls on FF's	05/13/2007 2008	02/17/2007 1630
07-0000804	Electrical arc causes fire, creates hazard for FFs.	03/16/2007 1223	03/15/2007 0830
13-0000321	Good SA anticipates imminent flashover.	05/08/2013 0807	01/10/2010 0000
10-0000697	Incident commander recognizes collapse indicators.	04/09/2010 1717	01/01/1998 0900
10-0000069	Disoriented FF falls down stairs.	01/12/2010 1813	01/07/2010 0430
09-0000990	Crews caught in roll-over, communications blamed.	11/14/2009 1032	11/09/2009 0330
09-0000413	Changing fire conditions require good accountability.	04/11/2009 1105	10/20/1997 2200
09-0000392	Auger truck hits buried cable.	04/09/2009 1052	04/01/2009 0000
09-0000353	FF loses footing on snow covered roof.	04/03/2009 1314	01/01/2009 0130
09-0000071	Signs and symptoms ignored leading to flashover.	01/27/2009 2343	01/27/2009 0000
08-0000365	Debris from roof almost hits firefighter.	08/04/2008 1058	06/13/2008 1420
08-0000327	Hidden potential of collapse.	07/13/2008 2322	06/16/2008 0000
08-0000016	FF learns the importance of full PPE	01/09/2008 2352	12/15/2007 1400
07-0000726	Truss roof collapse causes near miss at church fire.	02/13/2007 0420	01/13/2007 2245
12-0000273	Crews reposition just as roof collapses.	12/03/2012 0705	11/26/2012 1700
Report Number	Report	Report Date	Event Date

12-0000243	Water tower operation threatens interior crew.	08/31/2012 2251	07/27/2012 1730
12-0000242	Windy conditions contribute to flashover.	08/30/2012 1629	01/18/2012 1025
12-0000218	Lightning struck chimney falls during extinguishment.	07/24/2012 1133	07/12/2012 1310
12-0000140	Loose SCBA strap is an entanglement hazard.	05/15/2012 1757	05/03/2012 1515
12-0000100	Sounding the floor prevents injury.	04/02/2012 1000	03/31/2012 1700
12-0000089	Simultaneous interior/exterior attack.	03/25/2012 1302	03/11/2012 1132
12-0000086	Interior hose crew jeopardized by exterior fire attack.	03/21/2012 1505	03/11/2012 1300
11-0000414	Crew integrity compromised during search and attack.	12/29/2011 0015	09/20/2011 0030
11-0000343	Downed powerline inhibits fire attack.	11/13/2011 1735	10/07/2011 1400
11-0000299	Townhouse design challenges FFs.	09/13/2011 1635	09/01/2011 0130
11-0000040	Trapped FF has to self rescue.	01/26/2011 1628	12/16/2010 0030
10-0001146	Facepiece becomes tangled in debris.	10/14/2010 1652	10/13/2010 1600
10-0001076	Floor collapses under search team.	08/31/2010 1554	05/05/2005 1343
10-0001067	Stair collapses during search.	08/18/2010 1228	08/13/2010 0000
10-0000953	Chimney collapses during fire attack.	07/10/2010 1456	07/06/2010 0330
10-0000938	Trapped FF rescued during multi-alarm fire.	07/06/2010 1201	12/22/1999 2200
10-0000929	Downed power line overlooked during fire.	07/01/2010 1301	06/30/2010 1430
10-0000860	Hesitation proceeds floor collapse.	06/21/2010 0711	09/15/1984 0600
10-0000834	FFs narrowly escape danger inside bucket.	06/10/2010 1834	03/15/2010 0900
10-0000830	Fire rekindles while FFs are in rehab.	06/10/2010 1758	03/10/2010 0830
10-0000828	Floors collapse at 2-story house fire.	06/10/2010 1745	06/13/2006 0300
10-0000807	FFs caught in aerial platform by fire.	06/05/2010 1040	03/14/2009 0800
10-0000722	Interior crew hit with master stream.	04/21/2010 1624	04/18/2010 1853
10-0000685	Fire envelopes crew too near a window.	04/04/2010 1311	10/03/2009 1300
10-0000672	Fire found between roofs.	04/02/2010 1418	12/14/2000 2200
10-0000649	Safety officer prevents injuries.	03/30/2010 1914	03/07/2002 2000
10-0000633	Miscommunication results in electrical hazard.	03/30/2010 1718	02/25/2010 0430
10-0000631	Lieutenant saves FF from falling through roof.	03/30/2010 1711	02/25/2010 0430
10-0000561	Unsuccessful fire attack leads to bailout.	03/25/2010 1443	05/01/2000 1300
10-0000548	Falling debris injures FFs on ground ladders.	03/25/2010 1031	08/08/1989 0045
10-0000534	Crews pull out prior to collapse.	03/24/2010 1134	03/20/2005 1015
10-0000533	Crews disregard orders to evacuate.	03/24/2010 1122	11/15/1997 0230
10-0000528	Hole in floor poses FF hazard.	03/24/2010 1118	06/09/2007 0000
10-0000515	Recreation time lapses during attack.	03/24/2010 1102	09/04/2004 0000
10-0000512	FF loses control of line on icy roof.	03/24/2010 1002	01/15/2010 0900
10-0000511	Message relayed was not message received.	03/23/2010 2246	04/11/2005 0600
10-0000468	Floor collapse after fire is knocked down.	03/13/2010 1016	12/01/1998 0200
10-0000447	Drywall ceiling comes down during overhaul.	03/11/2010 1636	09/02/2009 0230
10-0000420	Advanced fire upon arrival at multi-family dwelling.	03/10/2010 2045	12/15/2008 0400
10-0000419	Brick veneer wall collapses during attack.	03/10/2010 2032	03/17/2008 2300
10-0000376	Backing tower ladder almost hits another ladder truck.	03/08/2010 2038	12/15/2009 0630
10-0000347	Delayed water supply puts search crew at risk.	03/04/2010 1100	07/01/2008 2200
Report Number	Report	Report Date	Event Date

10-0000337	Spongy floor allows FF to fall into fire.	03/04/2010 1038	12/10/2006 0000
10-0000297	Personal issues distract FF on roof.	02/19/2010 1107	10/10/1993 1600
10-0000251	Delay in hose stretch saves FFs.	02/09/2010 1413	08/01/2007 0000
10-0000245	Stairway collapses under FF during attack.	02/09/2010 1251	03/15/1992 0000
10-0000085	FF protected from falling by partner.	01/12/2010 2322	03/01/1990 1000
10-0000082	Doorway protects FF from falling drywall.	01/12/2010 2258	05/29/2007 1300
10-0000074	Falling debris traps FF during fire attack.	01/12/2010 2128	07/18/1979 1730
10-0000059	Floor collapses during aggressive attack.	01/11/2010 1250	02/13/2000 1000
10-0000037	Communication breakdown causes unwanted ventilation.	01/09/2010 1040	12/05/2010 2300
10-0000026	Floor system fails during fire attack.	01/08/2010 1033	05/25/2002 1000
10-0000024	Hidden fire results in floor collapse at apartment fire.	01/08/2010 1028	03/01/2008 0200
09-0001146	Missed 360 survey contributes to burn injury.	12/26/2009 1503	07/16/2009 1711
09-0001101	Facepiece ripped off while descending a ladder.	12/13/2009 1849	08/17/2009 2015
09-0001072	FF enters IDLH environment without SCBA.	12/09/2009 2117	09/01/2007 1535
09-0001065	Multiple hose lines confuse exiting crew.	12/08/2009 0608	06/02/1992 0000
09-0001013	Pre-control overhaul causes a backdraft.	11/17/2009 1057	10/21/2009 0500
09-0000969	Roof collapse knocks firefighter to the ground.	10/31/2009 1623	05/18/1995 1400
09-0000886	FF falls through ceiling at house fire.	09/19/2009 0908	03/15/1980 1600
09-0000606	Hoseline burns as victim is rescued.	06/25/2009 2038	06/13/1992 0030
09-0000542	Shut the hydrant off before disconnecting hose.	05/30/2009 1403	05/12/2009 0100
09-0000517	Chair prevents FFs from falling through floor.	05/21/2009 2007	10/10/1998 2200
09-0000465	Structural collapse threatens attack crews.	05/04/2009 2100	05/02/2009 0800
09-0000441	Good decision making averts injuries or fatalities.	04/26/2009 1107	04/20/2009 0000
09-0000415	Debris thrown from high-rise can be hazardous.	04/11/2009 1116	07/14/2005 2100
09-0000365	Offensive attack goes defensive.	04/06/2009 1101	12/13/2008 1400
09-0000337	Ladder falls with FF.	03/31/2009 1905	05/01/2003 1800
09-0000335	Ceiling collapses on firefighters.	03/31/2009 1838	03/16/2009 1600
09-0000250	Order to evacuate prevents injury from collapse.	03/06/2009 1506	01/10/2009 2230
09-0000246	Relocating attack line proves unwise.	03/06/2009 1402	02/01/1989 0300
09-0000245	Saw operator kicks backup man.	03/06/2009 1346	01/01/2008 1400
09-0000229	Crew enters fire with dry hoseline.	03/01/2009 2259	01/24/2009 2000
09-0000221	Hidden fire endangers attack crew.	02/28/2009 1125	08/01/2008 1900
09-0000171	Underestimated fire conditions endangers FF.	02/13/2009 0933	01/12/2009 0259
09-0000147	Stairs fall on firefighters during overhaul.	02/06/2009 1125	10/10/2005 0200
09-0000096	RIT crew rescues FF from structural collapse.	02/02/2009 0837	12/01/2008 2200
09-0000095	Explosion under apparatus from electrical vault.	02/02/2009 0829	11/15/2008 2000
09-0000058	Engine crew question risk vs benefit.	01/19/2009 1737	01/19/2009 0200
08-0000594	Gas leak causes explosion.	11/13/2008 1504	12/30/2006 1830
08-0000579	Electrical lines dictate tactical decisions.	11/09/2008 1011	01/31/2004 0543
08-0000505	Delay in critical info relayed to crews.	10/07/2008 1341	08/08/2008 0900
08-0000482	Floor collapses FF saves self.	09/29/2008 1449	11/20/2004 0100
08-0000466	Collapse threatens firefighters.	09/23/2008 2011	05/01/1997 0600
08-0000463	Ventilatin section slides off roof almost hits FFs.	09/23/2008 0958	02/05/2005 1300
Report Number	Report	Report Date	Event Date

08-0000377	Delayed water plus explosion equal near disaster.	08/13/2008 1629	07/14/2008 2210
08-0000362	FF mayday event results after collapse.	07/31/2008 2005	06/28/2008 0156
08-0000254	Falling power lines just miss FF raising ladder.	05/21/2008 0841	10/08/2004 1000
08-0000201	Fire fighters trapped on roof	04/28/2008 1249	10/01/2007 0124
07-0000860	FF nearly falls through floor	04/11/2007 1032	01/14/2006 0715
07-0000857	Drop in water pressure during fire attack leads to injuries.	04/10/2007 1300	03/21/2007 0542
07-0000788	FF bumps tower ladder controls, causing accidental movement.	03/10/2007 1430	12/01/2006 0000
07-0000761	Failure to lock dogs retracts ladder.	03/02/2007 0830	02/27/2007 2032
07-0000742	Loss of situational awareness leads to FFs being burned at structure fire.	02/24/2007 1304	10/15/2005 0300
05-0000413	Collapsing stucco facade narrowly misses firefighters.	08/08/2005 0023	10/11/1994 0300
05-0000292	Firefighters trapped; escape over ground ladder.	06/06/2005 1343	02/16/1983 0700
12-0000153	Ladder pipe damaged while nesting the aerial.	05/31/2012 1012	05/14/2012 2315
11-0000326	Mayday called when FF falls into basement at church fire.	10/26/2011 1119	09/19/2011 0300
11-0000250	Additional fire discovered during the incident hot wash.	07/07/2011 1237	06/30/2011 0340
11-0000247	Additional fire discovered during hot-wash.	07/05/2011 2149	06/30/2011 0340
11-0000133	Haste results in accidents at dumpster fire.	04/01/2011 0658	03/18/2011 1630
10-0001271	Carport collapses during attack.	12/12/2010 2052	12/11/2010 2230
10-0001255	Bell falls from burning bell tower.	12/03/2010 1458	03/29/1994 0000
10-0001206	Firefighter avoids injury by wearing his helmet.	11/29/2010 1230	08/17/2010 1600
10-0000726	Ceiling drops during interior attack.	04/26/2010 1920	01/17/2010 1025
10-0000693	Building conditions not suitable for training.	04/08/2010 1025	10/10/2005 1300
10-0000669	Roof collapses on interior crews.	04/02/2010 1318	03/10/2010 1100
10-0000663	Indicators of collapse not accounted for by command.	04/01/2010 1134	11/24/1999 0500
10-0000615	FF falls down stairs during overhaul.	03/27/2010 2139	12/15/2007 1200
10-0000481	First floor burned out prior to entry.	03/14/2010 1304	11/01/1997 2330
10-0000341	FF covered in fuel during overhaul.	03/04/2010 1047	12/22/1987 2210
10-0000252	Escape route blocked endangers FFs.	02/09/2010 1419	05/05/2005 0000
10-0000240	Master stream to the roof causes collapse.	02/07/2010 2143	03/01/2008 1300
10-0000212	FF thrown from ladder after opening nozzle.	02/02/2010 1452	08/25/2009 2200
10-0000016	LPG tank discovered during overhaul.	01/08/2010 1019	01/01/1988 2300
09-0001136	FF struck on head by 6x6 piece of lumber.	12/23/2009 0146	02/01/2002 2100
09-0001111	Coupling fails and nearly caused injury.	12/18/2009 0201	11/01/1996 1600
09-0001106	Lack of training causes difficulty.	12/17/2009 1153	02/28/2008 0200
09-0001059	Roof collapses during fire attack.	12/07/2009 2124	07/05/2007 0100
09-0000994	FFs walk over live power lines.	11/15/2009 1144	07/12/2005 1700
09-0000871	Boat fire presents difficult situation for FFs.	08/29/2009 2048	03/05/1983 0200
09-0000843	Crew runs out of water.	08/27/2009 0908	12/24/2004 2030
09-0000817	Water and grade cause problems with ladder operations.	08/24/2009 1112	04/01/2008 0000
Report Number	Report	Report Date	Event Date

09-0000764	Falling power line threatens FFs.	08/20/2009 0929	10/12/2007 2008
09-0000757	Proper donning of SCBA saves FF.	08/17/2009 1542	07/17/2009 2100
09-0000745	Firefighters gets disoriented and entangled.	08/09/2009 0630	09/18/2008 2229
09-0000692	Grain elevator explodes during extinguishment.	07/16/2009 0934	09/01/1985 1000
09-0000686	Plunge-cut with saw endangers FFs.	07/15/2009 1654	08/21/2000 1700
09-0000511	Firefighter falls through floor at mobile home.	05/21/2009 1956	06/13/2006 1500
09-0000406	Building power line drops on engine.	04/10/2009 2135	02/23/2009 0025
09-0000344	Fireball engulfs FFs at trailer fire.	04/02/2009 1225	03/31/2009 1835
09-0000338	Roof section falls on FF.	03/31/2009 2052	04/16/2002 1800
09-0000290	Supply hose drags behind engine, hits FF.	03/14/2009 1121	12/22/2008 1900
09-0000258	Apparatus overturn by inexperienced driver.	03/08/2009 2040	12/08/2008 2300
09-0000227	Supply line knocks FF to the ground.	03/01/2009 0028	02/12/2009 0230
09-0000217	Wall collapse narrowly misses FF.	02/28/2009 1122	06/01/1990 1800
09-0000215	Floor collapses as FFs exit.	02/28/2009 1121	02/02/2009 2300
09-0000149	Engine company endangered under brick gable.	02/06/2009 1125	10/10/2008 1100
09-0000089	High wind blows off roof section toward FFs.	01/30/2009 1008	12/28/2008 0300
09-0000072	Company falls through compromised porch roof.	01/27/2009 2352	01/21/2009 1800
09-0000015	Loss of crew integrity jeopardizes operation.	01/10/2009 2208	01/08/2009 1530
08-0000640	Paramedic struck by debris from fire.	12/06/2008 2020	12/02/2008 0600
08-0000632	Unsafe practice found during barn fire.	12/06/2008 1247	10/26/1984 2030
08-0000577	Lieutenant falls through floor.	11/07/2008 1553	11/05/2008 0400
13-0000305	Simultaneous interior/exterior attack.	02/25/2013 1440	01/02/2013 1507
13-0000301	Crew trapped by flashover.	02/14/2013 2032	02/11/2013 1423
12-0000271	Unit officer calls Mayday for trapped firefighter.	11/25/2012 1954	11/25/2012 0730
12-0000260	Well below basement window proves hazardous.	11/07/2012 1456	11/04/2012 1152
12-0000247	Vent team member falls through roof.	09/09/2012 2234	09/09/2012 1430
12-0000234	Civilian endangered by firefighting activity.	08/14/2012 1516	07/05/2012 2100
12-0000227	Adverse heat drives interior crew out.	08/07/2012 1948	07/14/2012 1850
12-0000221	Fire not found in initial size-up location.	08/01/2012 1719	07/09/2012 1845
12-0000215	Crew member falls through floor.	07/17/2012 1547	07/16/2012 2230
12-0000177	Dirty lens nearly causes FF to fall.	06/20/2012 2146	12/24/2007 0000
12-0000162	Officer steps through floor during fire attack.	06/07/2012 1900	03/02/2012 1500
12-0000161	Hole traps FF during overhaul.	06/07/2012 1725	02/28/2002 0000
12-0000152	Low air supply forces crew to seek egress.	05/29/2012 0547	04/04/2011 0200
12-0000143	Welds break on aerial during fire attack.	05/18/2012 1948	05/15/2012 0030
12-0000141	Firefighters burned worse than originally thought.	05/16/2012 1924	05/16/2012 1050
12-0000130	Two simultaneous fires create confusion.	05/08/2012 1019	11/13/2011 1830
12-0000117	Floor burned away prior to entry by attack crew.	04/19/2012 0411	04/19/2012 0110
12-0000108	Officer falls from roof during ventilation.	04/11/2012 1647	06/01/1988 1400
12-0000101	Lithium batteries explode during overhaul.	04/03/2012 2114	03/29/2012 0109
12-0000087	Interior attack inhibited by exterior crew.	03/21/2012 1544	03/11/2012 1132
12-0000075	Power line falls across engine at structure fire.	03/18/2012 1915	12/28/2011 2035
12-0000074	Good SA helps spot electrical hazard.	03/12/2012 1031	03/11/2012 0000
12-0000072	LEO fires weapon during firefighting operation.	03/09/2012 1935	07/13/2011 1707
Report Number	Report	Report Date	Event Date

12-000070	Ventilation helps protect attack crew..	03/06/2012 1846	08/18/2011 1933
12-000063	Kinked line causes water delay.	02/28/2012 2337	01/27/2012 1956
12-000062	Wire causes roof ladder to snap back.	02/28/2012 1919	02/26/2012 1310
12-000033	Attic stairs trap FF in flashover.	02/09/2012 1535	02/14/2011 1720
12-000027	Good communication keeps everyone safer.	02/06/2012 2143	02/06/2012 1130
12-000010	Good SA protects FFs at structure fire.	01/19/2012 1023	12/14/2011 1302
11-0000382	Roof gives way under FF during ventilation.	12/06/2011 1401	12/05/2011 2245
11-0000347	Hidden fuel tank explodes during fire attack.	11/15/2011 1759	11/13/2011 0840
11-0000330	Ceiling collapses on FF during overhaul.	10/26/2011 1638	10/25/2011 0430
11-0000305	Building collapse grabs three FFs.	09/27/2011 1154	08/28/2011 0200
11-0000270	Lack of both experience and water hamper fire attack.	08/07/2011 2042	06/11/2011 0800
11-0000267	Lack of railing results in 2 story fall.	08/06/2011 0013	08/03/2011 1700
11-0000264	Safety Officer calls MAYDAY during overhaul.	08/02/2011 1436	01/18/2007 1200
11-0000257	Overhaul operations result in FF injury.	07/23/2011 1450	07/02/2011 2300
11-0000249	Charged 5 inch line injures two firefighters.	07/06/2011 2025	06/15/2011 0000
11-0000214	Dormer collapses during attack.	05/26/2011 2158	05/13/2011 1800
11-0000163	Unseen electrical line endangers FF.	04/30/2011 1042	04/28/2011 0330
11-0000146	Roof collapses as FFs enter house.	04/12/2011 2048	05/24/2009 0425
11-0000145	No PPE or SCBA worn during fire attack.	04/12/2011 2044	03/19/2011 0312
11-0000144	Exposure to byproducts of combustion at meth lab.	04/12/2011 2038	03/19/2011 0312
11-0000124	Floor collapses from rot not fire.	03/28/2011 1147	12/12/1975 1455
11-0000120	Crew integrity lost during fire attack.	03/27/2011 1321	03/20/2011 1533
11-0000108	Vent team loses footing on roof.	03/10/2011 1813	11/23/2008 2058
11-0000094	Crew trapped by rapidly changing conditions.	02/17/2011 2300	02/14/2011 0845
11-0000075	Radio traffic prevents progress updates.	02/10/2011 0329	02/01/2011 0000
11-0000074	Insignificant radio traffic inhibits attack.	02/10/2011 0306	02/01/2011 2300
11-0000071	Unstable floor temporarily traps FF.	02/08/2011 1429	07/26/2010 2214
11-0000068	Never abandon your weapon.	02/04/2011 1501	01/15/2008 1000
11-0000056	Buddy system breakdown puts FFs at risk.	02/04/2011 1117	12/15/1982 2200
11-0000055	Hood strut becomes projectile during car fire.	02/04/2011 1107	01/15/2011 0900
11-0000054	Natural gas meters fails during interior attack.	02/04/2011 1054	04/01/1992 1500
11-0000053	PPE reduces injury potential to FF.	02/04/2011 1047	04/12/2009 1730
11-0000044	Catastrophic floor collapse during fire attack.	01/31/2011 1042	01/27/2011 0530
11-0000043	Snow causes FF to fall.	01/30/2011 1259	01/28/2011 1500
11-0000041	Crew recognizes sagging floor and backs out.	01/27/2011 0057	12/27/2010 2245
11-0000039	Garage door poses uncommunicated threat.	01/25/2011 1939	01/24/2011 0225
11-0000038	Officer initiates mayday at structure fire.	01/24/2011 1414	01/14/2011 2310
11-0000034	Mayday called by lost firefighter.	01/24/2011 1335	12/22/2010 0830
11-0000024	FF falls through floor during secondary search.	01/20/2011 1819	11/30/2010 0300
11-0000023	Flames engulf FF doing overhaul.	01/19/2011 1526	01/16/2011 1400
11-0000016	Missing adapter threatens water supply.	01/18/2011 1019	10/31/2010 0325
11-0000008	Hose stream knocks over chimney near crew.	01/10/2011 1318	01/01/2011 1807
10-0001290	Stove fire quickly grows with help from wind.	12/30/2010 1519	09/30/2010 1445
10-0001267	Static discharge shocks FF using CO2 extinguisher.	12/04/2010 0740	03/30/2010 1300

Report Number

Report

Report Date

Event Date

10-0001227	PPV fans cause hazard for interior crew.	12/01/2010 1206	08/10/2006 1530
10-0001210	Egress blocked by overlooked fire.	11/29/2010 1235	11/20/2004 0200
10-0001197	Structure energized during meter incident.	11/19/2010 0727	08/30/2010 0930
10-0001182	Gas filled room flashes when FFs enter.	11/08/2010 0731	03/15/2006 2000
10-0001179	Live wire falls near FF.	11/08/2010 0654	09/14/1998 2100
10-0001141	Driver begins to move rig with FF underneath.	10/07/2010 1530	06/09/2009 1900
10-0001139	Fallen power line and PPE ignored at structure fire.	10/06/2010 1448	09/24/2010 1500
10-0001119	Roof collapses during fire fight.	09/26/2010 1207	04/24/1995 0000
10-0001118	Freelancing during structure fire.	09/25/2010 1329	09/24/2010 1654
10-0001111	Crew backs out after finding floor unsafe.	09/23/2010 1528	08/15/2007 0730
10-0001110	Sleepy FF steps off ladder during fire.	09/23/2010 1504	08/11/2007 0500
10-0001107	Cast iron tub falls through floor during a structure fire.	09/23/2010 1446	07/02/2007 1400
10-0001103	Lieutenant slips from ladder.	09/23/2010 1139	04/15/2007 2100
10-0001092	Alert crew warns entry team of hole in floor.	09/17/2010 1157	11/10/2005 1800
10-0001082	Chimney collapse threatens crew.	09/10/2010 1150	12/17/2003 1700
10-0001081	Survival training comes into play following collapse.	09/07/2010 1951	01/01/2010 0000
10-0001064	Stairs collapse during search.	08/17/2010 1651	07/20/2010 0130
10-0001054	Safety officer ignored during farm house fire.	08/13/2010 1704	06/30/2010 1700
10-0001053	FF bails out of second floor window.	08/13/2010 1700	05/15/2010 1200
10-0001052	Equipment damaged during house fire.	08/13/2010 1657	04/15/2010 1000
10-0001047	Firefighter injuries knee while focused on attic fire.	08/12/2010 1234	04/17/2010 2350
10-0001046	Inexperienced FF finds a way out.	08/12/2010 0943	04/26/1985 1000
10-0001043	Relief crew not informed of hazard.	08/11/2010 1501	03/05/1998 0130
10-0001118	Freelancing during structure fire.	09/25/2010 1329	09/24/2010 1654
10-0001111	Crew backs out after finding floor unsafe.	09/23/2010 1528	08/15/2007 0730
10-0001110	Sleepy FF steps off ladder during fire.	09/23/2010 1504	08/11/2007 0500
10-0001107	Cast iron tub falls through floor during a structure fire.	09/23/2010 1446	07/02/2007 1400
10-0001103	Lieutenant slips from ladder.	09/23/2010 1139	04/15/2007 2100
10-0001092	Alert crew warns entry team of hole in floor.	09/17/2010 1157	11/10/2005 1800
10-0001082	Chimney collapse threatens crew.	09/10/2010 1150	12/17/2003 1700
10-0001081	Survival training comes into play following collapse.	09/07/2010 1951	01/01/2010 0000
10-0001064	Stairs collapse during search.	08/17/2010 1651	07/20/2010 0130
10-0001054	Safety officer ignored during farm house fire.	08/13/2010 1704	06/30/2010 1700
10-0001053	FF bails out of second floor window.	08/13/2010 1700	05/15/2010 1200
10-0001052	Equipment damaged during house fire.	08/13/2010 1657	04/15/2010 1000
10-0001047	Firefighter injuries knee while focused on attic fire.	08/12/2010 1234	04/17/2010 2350
10-0001046	Inexperienced FF finds a way out.	08/12/2010 0943	04/26/1985 1000
10-0001043	Relief crew not informed of hazard.	08/11/2010 1501	03/05/1998 0130
10-0001035	All hazards need to be secured.	08/05/2010 1643	05/09/1983 1400
10-0001034	Fire flashes on overhaul crew.	08/05/2010 1634	02/02/2008 2100
Report Number	Report	Report Date	Event Date

10-0001032	Uncoordinated attack puts FFs in jeopardy.	08/05/2010 1507	04/06/2006 1230
10-0001027	SCBA bottle not fully opened prior to entry.	08/05/2010 1224	04/09/2009 1600
10-0001026	Floor gives way during overhaul.	08/05/2010 1209	03/03/2008 1400
10-0001014	Large residential structure burns out of control.	07/25/2010 1600	05/20/2009 1840
10-0001011	Unenclosed well discovered during attack.	07/25/2010 1504	05/01/2010 0430
10-0001010	Delayed ventilation contributes to flashover.	07/25/2010 1454	07/01/2010 0800
10-0001009	FF injured by saw.	07/25/2010 1453	07/19/2010 0645
10-0001004	Basement fire traps lone FF.	07/24/2010 1630	07/01/2010 2200
10-0000999	Officer separates from crew during attack.	07/24/2010 1434	09/30/2008 1500
10-0000981	Overhang collapses at structure fire.	07/15/2010 1527	07/04/1998 0030
10-0000979	Poor communication on fireground.	07/15/2010 1500	10/23/2003 0930
10-0000975	Lack of PPE leaves FF with injuries.	07/15/2010 1425	03/03/2003 1300
10-0000971	Disoriented FFs call "Mayday."	07/15/2010 1317	02/20/2010 0400
10-0000970	Savvy officer saves crew from collapse.	07/15/2010 1249	09/17/2005 0700
10-0000969	Explosion sends shrapnel flying.	07/15/2010 1203	05/12/2009 1300
10-0000966	Good entry practice alerts crew to danger.	07/14/2010 1250	07/12/2010 0130
10-0000958	Attack crew backs out due to heat.	07/13/2010 0954	11/01/1999 0200
10-0000956	Sagging electrical wires ignored during fire attack.	07/12/2010 2108	04/14/2010 1100
10-0000952	Smoke explosion in gable roof.	07/09/2010 1113	06/24/2010 1030
10-0000940	Roof collapses during overhaul.	07/06/2010 1233	06/01/2010 1600
10-0000901	Flashover surprises investigating crew members.	06/30/2010 1212	11/21/2009 1800
10-0000883	Ceiling collapses on attack crew.	06/24/2010 1038	01/10/2009 1300
10-0000870	Fire crews leaves roof just before collapse.	06/22/2010 1000	03/01/2010 1630
10-0000861	Floor collapses during fire attack.	06/21/2010 1650	05/01/2010 1900
10-0000855	Chimney falls down behind FF.	06/17/2010 1810	06/13/2010 0400
10-0000823	Previously burned structure proves hazardous.	06/09/2010 1833	03/26/2010 0200
10-0000822	Fire floor flashes prior to entry.	06/09/2010 1819	08/15/2009 0900
10-0000819	FFs caught off guard when attic flashes.	06/09/2010 1742	03/14/2009 0000
10-0000805	FF falls through damaged roof.	06/05/2010 1033	10/26/2009 0000
10-0000801	Downed power lines hinder operations.	06/05/2010 1032	09/09/1999 0000
10-0000791	Attack crew encounters extreme heat.	06/04/2010 2318	04/02/2001 1400
10-0000755	Flashover occurs while crew is evacuating.	05/18/2010 1005	06/16/2009 0140
10-0000753	Energized house causes problems for FFs.	05/18/2010 1001	10/15/2010 1830
10-0000725	Burning deck endangers attack crew.	04/23/2010 0819	04/22/2010 2350
10-0000702	Ammunition fires during interior attack.	04/12/2010 0940	04/11/2010 0945
10-0000694	Partial collapse occurs when checking for extension.	04/08/2010 1624	02/01/1997 2200
10-0000664	SCBA not worn during roof operations.	04/01/2010 1140	04/11/1994 0000
10-0000651	Crews enter after defensive fire called.	03/31/2010 0025	03/22/2010 1830
10-0000647	Quicker communication needed in collapse event.	03/30/2010 1854	01/01/2008 0200
10-0000642	Kinked hose stalls attack, injures firefighters.	03/30/2010 1810	07/14/2003 2330
10-0000641	Wire falls as FF approaches fire.	03/30/2010 1757	03/15/2007 0630
10-0000634	Lack of 360 leads to unnecessary risk at fire.	03/30/2010 1727	08/01/2002 0200
10-0000632	Ceiling falls on FF in mobile home fire.	03/30/2010 1716	06/01/2000 1100

Report Number

Report

Report Date

Event Date

10-0000629	Evacuation signaled at mobile home fire.	03/30/2010 1651	09/01/2003 0200
10-0000625	Simultaneous offensive and defensive operations.	03/29/2010 1942	05/20/2008 1400
10-0000617	Ladder slips on concrete driveway.	03/27/2010 2157	09/15/2009 2000
10-0000604	Lack of ventilation leads to backdraft.	03/27/2010 1122	06/01/1988 0200
10-0000601	Gravel clogs nozzle during fire attack.	03/27/2010 1102	11/24/1999 2200
10-0000586	Garage door knocked down onto firefighter.	03/26/2010 1509	07/01/2003 2130
10-0000574	FF falls through floor into basement.	03/25/2010 1636	05/01/2009 1830
10-0000572	FF gets lost in basement with no radio.	03/25/2010 1610	05/01/2009 0000
10-0000557	FF falls from ladder uninjured.	03/25/2010 1350	09/12/2002 1900
10-0000555	FF walks into lowering ladder.	03/25/2010 1339	03/06/2010 1430
10-0000546	Chimney fire overhaul creates hazard.	03/24/2010 2308	12/06/2009 1900
10-0000530	Downed power line almost stepped on at fire.	03/24/2010 1119	02/17/2006 0530
10-0000526	Conflicting assignments lead to injuries.	03/24/2010 1113	06/10/1988 0417
10-0000524	Garage door pushed onto FF operating alone.	03/24/2010 1113	02/02/1996 2200
10-0000520	Debris thrown out window almost hits FF.	03/24/2010 1111	01/20/2010 0000
10-0000503	Crew questions officer's decision to make entry.	03/23/2010 2136	02/10/1992 0130
10-0000502	Construction features hide fire conditions from crew.	03/23/2010 2118	06/01/2005 0530
10-0000500	Communication becomes issue during fire.	03/23/2010 2048	12/01/2009 2000
10-0000484	House collapses during defensive attack.	03/14/2010 1334	10/12/2009 1800
10-0000479	Crew ignores warning sign of impending collapse.	03/14/2010 1258	12/15/2009 2100
10-0000474	Nozzle FF steps through burned out staircase.	03/14/2010 1131	08/01/2008 1100
10-0000471	Crew falls through floor during fire attack.	03/13/2010 1848	04/15/2009 2115
10-0000462	Floor collapses during attack.	03/12/2010 1854	05/05/1998 1155
10-0000449	Water supply issues delay extinguishment.	03/11/2010 1643	01/10/2001 0000
10-0000421	Lack of experience becomes a factor for hose team.	03/10/2010 2057	04/15/1995 1900
10-0000417	Fire grows as handline is abandoned.	03/10/2010 1956	12/15/1999 1000
10-0000406	FFs caught in attic backdraft.	03/10/2010 0624	06/01/2007 2100
10-0000396	Lack of walk-around jeopardizes FFs.	03/09/2010 1428	10/10/2006 2300
10-0000390	Burned out floor causes FF to fall.	03/09/2010 1422	01/15/2009 2200
10-0000384	Collapse indicators recognized by command.	03/09/2010 1322	07/10/2001 1300
10-0000382	Fire in hung ceiling causes floor to collapse.	03/09/2010 1205	12/20/2009 1830
10-0000348	SCBA and PPE not worn by crews during salvage.	03/04/2010 1108	02/21/2010 0200
10-0000345	Building collapses during transitional attack.	03/04/2010 1052	11/16/2009 0230
10-0000344	Chimney begins to lean as FF attempts to vent.	03/04/2010 1051	01/20/2010 2100
10-0000338	Heavy chandelier falls during overhaul.	03/04/2010 1041	02/10/2010 0330
10-0000329	Crew becomes disoriented and calls MAYDAY.	03/03/2010 1249	12/28/2009 2123
10-0000327	Risky fire attack on a vacant structure.	03/02/2010 1715	04/02/2006 2000
10-0000325	Chimney collapse surprises everyone.	03/02/2010 1535	03/19/2009 0100
10-0000322	Debris strikes FF when thrown out window.	02/28/2010 1824	02/28/2010 0700
10-0000319	Extreme heat drives attack crew out of building.	02/26/2010 1559	07/16/2004 1400
10-0000317	FF almost falls off roof checking for extension.	02/26/2010 1022	12/02/1988 1600
10-0000311	Large hole missed upon entry into structure fire.	02/26/2010 0946	04/10/2006 0000
10-0000307	Rookie enters burning structure alone.	02/23/2010 0802	01/15/2007 0715
10-0000300	Opposing handlines narrowly avoid injury.	02/20/2010 1744	12/12/2009 1900

10-0000296	FF's gear receives extensive damage.	02/19/2010 1106	04/01/2000 0400
10-0000295	Circular saw strikes FF's leg.	02/19/2010 1104	07/04/2008 0000
10-0000280	Collapsing awning lands near officer.	02/12/2010 2027	05/05/2009 2200
10-0000277	Personnel fail to respond to PASS activation during fire.	02/12/2010 1057	02/09/2010 0237
10-0000273	RIT put to work and not replaced during attack.	02/11/2010 0934	11/28/2009 2156
10-0000264	FF falls through the ceiling during overhaul.	02/10/2010 1847	07/09/2007 0000
10-0000246	Contact with electrical panel results in shock.	02/09/2010 1257	07/20/2004 1500
10-0000232	Lack of SCBA results in smoke inhalation.	02/05/2010 1701	04/21/2009 1337
10-0000230	Crews evacuate due to collapse.	02/05/2010 1646	12/01/2008 1830
10-0000199	Haste on scene results in accident.	02/02/2010 1230	11/21/2009 1600
10-0000169	Spongy floor collapses during search.	01/23/2010 1720	11/20/2009 0740
10-0000163	Roof collapses on FFs during attack.	01/22/2010 1027	12/09/2009 1320
10-0000157	Good 360 and situational awareness saves crew.	01/20/2010 1804	05/08/2008 0615
10-0000155	Officer recognizes collapse indicators.	01/20/2010 1724	03/10/1995 0930
10-0000146	FF falls through the floor at a confirmed arson fire.	01/19/2010 1730	06/27/1997 1500
10-0000143	Axe slips, narrowly missing FFs.	01/19/2010 1417	02/15/2001 1700
10-0000134	Carport collapses on firefighters.	01/19/2010 1400	06/27/1993 1800
10-0000114	Vent crew cuts live wire and threatens attack crew.	01/16/2010 0144	10/15/2009 1100
10-0000073	Ladder not extended far enough at chimney fire.	01/12/2010 2128	01/04/2010 1900
10-0000070	Collapse occurs at garage fire.	01/12/2010 2124	11/14/2009 0000
10-0000064	Floor collapse at structure fire dumps FF in basement.	01/11/2010 1819	09/20/2003 0200
10-0000063	Evacuation gets crews out just before collapse.	01/11/2010 1806	08/11/1992 0100
10-0000052	Searcher falls through floor while using a TIC.	01/11/2010 0954	01/20/2004 0000
10-0000041	Crew trapped, chief discounts request for rescue.	01/09/2010 1054	12/19/2009 2020
10-0000039	Nozzleman falls through a reported spongy floor.	01/09/2010 1040	01/26/2008 1700
10-0000035	Missing PPE results in injuries.	01/09/2010 1030	08/14/2001 1800
10-0000031	LDH traps FF in ditch.	01/08/2010 1042	01/04/2010 1840
10-0000029	Burnt-out roof traps FF's leg during ventilation.	01/08/2010 1038	02/15/1990 0300
10-0000028	Crew becomes disoriented during basement fire.	01/08/2010 1038	10/23/2003 1730
10-0000022	FFs enter building with uncharged hoseline.	01/08/2010 1026	05/10/2003 1000
10-0000021	Safety officer nearly falls into snow covered pool.	01/08/2010 1026	02/02/2002 2300
10-0000020	FF gets off roof just before roof collapses.	01/08/2010 1024	01/23/1980 0000
10-0000019	Roof collapses on entry team.	01/08/2010 1024	03/10/2000 0900
10-0000010	Hidden fire chases attack crew.	01/07/2010 1456	01/04/2010 1330
09-0001152	Stairs found to be removed from basement landing.	12/31/2009 1144	12/29/2009 1725
09-0001122	FF steps on powerline and survives.	12/22/2009 1209	10/15/2009 2300
09-0001107	Officer narrowly avoids fall through floor.	12/17/2009 1235	12/01/2007 2000
09-0001080	Aerial overloaded at a working fire.	12/10/2009 1036	01/09/1990 1500
Report Number	Report	Report Date	Event Date

09-0001079	Ice on the roof causes FF to slip and slide.	12/10/2009 1035	02/20/2004 0000
09-0001077	Leg lock saves FF from fall.	12/10/2009 1032	05/10/1994 1800
09-0001047	FF Slips, trips and falls.	12/07/2009 1831	12/04/2005 1600
09-0001037	Shots fired during residential house fire alarm.	12/01/2009 1440	10/07/2008 2140
09-0001036	Oxygen tank explodes in fire causing injuries.	12/01/2009 1144	11/19/2009 0441
09-0001033	Rapidly changing conditions result in mayday.	11/26/2009 1400	11/21/2009 1745
09-0001019	Water supply lost and evacuation called.	11/17/2009 1100	05/22/2008 2200
09-0001015	Ceiling collapse injures FF during overhaul.	11/17/2009 1057	07/15/1999 2000
09-0001014	Lack of proper PPE causes burns to FFs at structure fire.	11/17/2009 1057	02/23/2009 0000
09-0001012	Heat causes FFs to back out of structure.	11/17/2009 1057	06/24/1999 0400
09-0001011	Crews stand on power line during operations.	11/17/2009 1057	12/11/1986 2236
09-0001009	FFs enter IDLH atmosphere without their officer.	11/17/2009 1056	07/12/2009 0600
09-0001005	FFs become disoriented and loose handline.	11/17/2009 1056	03/01/2007 1500
09-0000995	Flashover condition cause crews to evacuate structure.	11/15/2009 1328	09/21/2009 1300
09-0000993	Fire almost cuts off escape route.	11/15/2009 1040	12/10/2008 1945
09-0000987	FF falls through floor during overhaul.	11/14/2009 0535	12/24/2004 2200
09-0000967	Basement fire found by third due engine during 360.	10/31/2009 1549	06/01/2007 1120
09-0000964	Ceiling collapses on FFs.	10/31/2009 1455	08/22/1998 2230
09-0000930	FF struck in face by hose stream.	10/18/2009 0022	04/12/2009 2315
09-0000908	Quick action enables FFs to avoid power lines.	10/04/2009 1807	07/29/2009 0400
09-0000898	Incomplete 360 results in surprise at structure fire.	09/23/2009 0915	02/12/2009 1600
09-0000896	Cracking sound warns of wall collapse.	09/22/2009 1501	04/16/2007 1000
09-0000887	Opening hoseline blows clay tile off roof.	09/19/2009 1559	08/29/2009 1850
09-0000870	Burned out roof causes FF to fall.	08/29/2009 1850	06/28/2009 1630
09-0000853	Conditions deteriorate causing FFs to retreat.	08/28/2009 0704	08/13/2009 1500
09-0000815	FFs contact downed power line.	08/24/2009 1024	03/05/2005 2330
09-0000798	Lines down on fireground cause a problem.	08/21/2009 1147	06/22/2009 0130
09-0000791	FF falls through ceiling while checking the area.	08/21/2009 1108	01/01/1983 0800
09-0000789	Conflicting orders verified through command.	08/21/2009 1043	02/18/2004 2200
09-0000783	Burned out stairs cause adverse situation for FFs.	08/20/2009 1533	08/01/2009 1126
09-0000760	FFs electrocuted during overhaul.	08/18/2009 2220	11/22/1990 2300
09-0000737	Overhaul endagers FFs nearby.	08/06/2009 2037	03/15/2007 1200
09-0000736	Crew gives IC inaccurate information.	08/06/2009 1202	07/29/2009 2210
09-0000724	AC falls through roof near attack crew.	08/04/2009 1229	04/14/2005 2200
09-0000708	Glass injures FF while making forcible entry.	07/27/2009 1429	07/24/2009 2348
09-0000694	Building renovations and missing walls cause FF to fall.	07/16/2009 1008	11/22/1989 1900
09-0000688	Low visibility and missing handrail found on balcony.	07/15/2009 1721	09/09/2002 2200
09-0000687	Cluttered exit nearly traps FFs.	07/15/2009 1717	10/02/2006 2130
09-0000672	Staffing shortage almost leads to disaster.	07/12/2009 1559	07/09/2009 1400
09-0000669	Flashover causes FF's to evacuate.	07/10/2009 0905	02/12/1987 0200
Report Number	Report	Report Date	Event Date

09-0000668	Ceiling collapses on FF's.	07/09/2009 2333	07/09/2009 1442
09-0000654	Structure collapses unexpectedly.	07/07/2009 0853	07/12/2003 1400
09-0000653	Ceiling collapse injures FF.	07/06/2009 1414	07/11/2008 2106
09-0000651	Ventilation critical on basement fires.	07/02/2009 2321	07/12/2003 0200
09-0000644	Interior crews hindered by exterior attack.	06/30/2009 2333	08/13/2000 0900
09-0000643	Poor communication results in trapped FF.	06/30/2009 1855	12/05/2005 1900
09-0000640	FF cuts wrist breaking window.	06/30/2009 1137	05/04/2009 1300
09-0000637	Rescuers endangered by falling power line.	06/30/2009 1118	03/22/2008 1200
09-0000628	FFs caught in partial floor collapse.	06/30/2009 0946	06/01/2006 1830
09-0000581	Loss of water endangers attack crew.	06/13/2009 1158	02/05/1997 2300
09-0000579	Basement fire results in floor collapse.	06/13/2009 1057	06/13/1986 0200
09-0000574	Helmet prevents injury during rehab.	06/08/2009 1656	06/06/2009 0030
09-0000570	Roof collapses during mop-up operations.	06/06/2009 2010	12/01/2004 0145
09-0000566	Investigator falls through hidden floor damage.	06/06/2009 1932	03/01/2009 0600
09-0000544	Partial roof collapse occurs during firefighting.	05/31/2009 1748	05/30/2009 1348
09-0000523	Inexperienced, ill-equipped crew caught in smoke.	05/23/2009 0949	11/01/1980 2030
09-0000522	Flashover indicators and building conditions warrant evacuation of FFs.	05/23/2009 0914	05/17/2009 1600
09-0000509	Firefighter falls through collapsed floor.	05/21/2009 1652	12/24/2006 1400
09-0000498	FFs standing near downed power line.	05/19/2009 1036	04/13/2009 1313
09-0000491	Unsafe building threatens FFs during routine call.	05/15/2009 0119	05/13/2009 1655
09-0000477	Continual size-up on fireground essential to safety of firefighters.	05/06/2009 1144	12/07/2008 0420
09-0000461	Three minutes into attack floor collapses.	04/30/2009 1941	04/30/2009 2300
09-0000443	Front room flashover at mutual aid fire.	04/27/2009 1726	02/18/2004 0000
09-0000440	RIT rescues FFs during evacuation.	04/25/2009 1203	04/16/2009 0000
09-0000416	Smoke explosion injures FFs.	04/12/2009 1101	01/14/2009 0153
09-0000404	FF nearly falls into basement.	04/10/2009 1649	06/01/2005 0300
09-0000402	Burning car endangers FFs during fire attack.	04/09/2009 2029	04/09/2009 0105
09-0000400	SCBA mishap results in loss of crew integrity.	04/09/2009 1057	03/16/2009 0000
09-0000370	Basement fire attack results in injuries.	04/06/2009 1139	05/15/2002 0000
09-0000368	Attack crews injured during explosion.	04/06/2009 1116	11/14/2007 2145
09-0000358	Arson and backdraft conditions lead to problems.	04/05/2009 2134	05/01/1990 0100
09-0000343	Chimney collapses on firefighter.	04/02/2009 0959	03/01/2009 0000
09-0000329	Crew almost falls into basement fire.	03/30/2009 2222	10/25/1996 0800
09-0000328	Burning cabinets nearly crush firefighter.	03/30/2009 2207	09/20/2008 1500
09-0000306	Opposing hose lines almost burn FFs.	03/24/2009 1010	01/01/2002 0000
09-0000301	Hot powerline nearly electrocutes FF.	03/20/2009 1337	03/13/2009 2331
09-0000292	Flashover results in FF becoming disoriented.	03/14/2009 1132	05/22/2015 0230
09-0000252	FF falls through floor, unknown to others.	03/06/2009 1524	12/17/2007 0230
09-0000249	FF falls due to damage from previous fire.	03/06/2009 1429	02/25/2003 1400
09-0000238	Crew just makes it out of basement.	03/04/2009 0848	02/09/2007 0200
09-0000231	Attack line loses pressure during fire.	03/02/2009 1521	02/03/2009 0235

Report Number

Report

Report Date

Event Date

09-0000218	Communication not trusted almost leads to disaster.	02/28/2009 1125	04/01/2002 0000
09-0000211	IC orders everyone out before structure collapses.	02/27/2009 0730	02/20/2009 1714
09-0000203	Poor communication leads to uncoordinated attack.	02/24/2009 0941	10/12/2004 1110
09-0000193	New FFs raise ground ladder under wires.	02/22/2009 1043	11/26/2008 2100
09-0000187	Ladder heeler showered with glass.	02/22/2009 1037	02/07/2009 1100
09-0000173	Tree collapse narrowly misses FF.	02/13/2009 1944	02/09/2009 1130
09-0000164	Unforeseen fire conditions force retreat.	02/10/2009 1912	02/05/2009 1930
09-0000158	Simultaneous offensive and defensive ops prove dangerous.	02/06/2009 1501	10/15/2002 1024
09-0000152	Garage collapse almost takes out FF.	02/06/2009 1128	08/05/2008 1400
09-0000151	Driveshaft turns into projectile at garage fire.	02/06/2009 1126	08/20/1984 1700
09-0000120	Mask pulls off FF when harness is removed.	02/05/2009 0746	11/30/2007 2000
09-0000117	Alert crews evacuate structure fire just in time.	02/05/2009 0701	06/30/2008 1700
09-0000114	Out of air emergency in 2 story structure.	02/03/2009 1029	10/29/1997 0000
09-0000112	FFs suffer minor burns in flashover.	02/03/2009 1005	07/05/2008 1530
09-0000110	Attack crew caught in flashover.	02/03/2009 0957	01/23/2008 2148
09-0000085	Previous renovation plus fire equals collapse.	01/29/2009 0006	01/27/2009 0000
09-0000079	Take care of those utilities.	01/28/2009 2302	07/01/2007 0330
09-0000076	Hose hits porch supports.	01/28/2009 2235	08/15/2007 1600
09-0000069	Captain enters fire area alone and conditions deteriorate.	01/27/2009 2318	08/13/2006 1534
09-0000057	Flashover occurs as FFs ascend stairs.	01/18/2009 2240	06/01/2002 1300
09-0000051	Improper ladder carry endangers FF.	01/18/2009 1533	03/10/1985 2100
09-0000047	FF falls through floor during basement fire.	01/18/2009 1157	05/04/2008 0330
09-0000042	2 lessons; swimming pool and parallel truss construction.	01/17/2009 1201	12/25/2008 0006
09-0000027	Observant BC gets crew out of harm's way.	01/14/2009 0149	12/10/2007 2300
09-0000018	FF runs out of air due to entanglement.	01/12/2009 1048	01/10/2009 1200
09-0000016	Fire stream knocks over chimney and endangers crew.	01/11/2009 2352	02/24/2003 1300
09-0000013	FF shocked while moving live power line.	01/10/2009 0015	01/02/2009 2059
09-0000012	Freelancing endangers attack crew.	01/10/2009 0005	01/02/2009 2059
08-0000663	FF falls through floor into basement.	12/24/2008 1222	12/21/2008 1715
08-0000642	Changing conditions overrun hose team.	12/08/2008 1533	02/09/2003 1310
08-0000628	Porch collapse endangers attack crew.	12/06/2008 1244	12/16/1992 1930
08-0000615	Porch collapse traps officer.	11/24/2008 0057	11/23/2008 1840
08-0000604	FF falls off balcony.	11/19/2008 1600	03/05/2008 0720
08-0000600	CO explosion blows FFs out of structure.	11/13/2008 2359	04/03/2007 1600
08-0000599	FF falls into basement through burnt out floor.	11/13/2008 2335	07/12/1982 0900
08-0000523	Unexpected lightweight construction becomes a hazard.	10/20/2008 2224	06/13/2004 2350
08-0000518	Explosion during fire attack at residential structure.	10/17/2008 1006	10/12/2008 2316
08-0000508	Gunfire erupts during house fire.	10/10/2008 0930	09/07/2008 2200
Report Number	Report	Report Date	Event Date

08-0000496	FF thinks door is an escape window.	10/02/2008 1422	09/20/2008 0830
08-0000489	T.I.C. alerts crew to hole in floor.	10/01/2008 1340	09/30/2008 0030
08-0000474	Fire attack crew egress cut off.	09/26/2008 1233	06/13/2002 1400
08-0000467	Firefighters injured during fire attack.	09/24/2008 1140	02/13/2008 0300
08-0000462	Ventilation crew steps through roof.	09/23/2008 0938	05/01/1994 1800
08-0000459	Downed electrical line poses hazard to FF.	09/20/2008 2134	02/01/2005 0100
08-0000455	Dry tank is no match for a house fire.	09/20/2008 1416	09/11/1991 0300
08-0000449	Basement fire surprises FFs.	09/19/2008 1957	12/24/1995 1400
08-0000446	Experience retreats FFs at flashover.	09/19/2008 1158	09/18/2008 0800
08-0000433	Suggestion to reposition line could have sustained injury.	09/12/2008 2155	09/11/2008 1130
08-0000428	Garage doors come down trapping OIC.	09/08/2008 2115	09/06/2008 1730
08-0000424	Floor collapses at basement fire.	09/07/2008 1331	11/02/2001 0100
08-0000423	Drive shaft explodes; sticks in ground behind pumper.	09/07/2008 1304	12/12/1995 0100
08-0000422	Covered porch falls near firefighters	09/07/2008 1246	11/01/1991 2200
08-0000417	FF left alone on roof during ventilation.	09/06/2008 1311	07/03/1996 1500
08-0000393	FF operating alone and standing in heavy fire conditions.	08/22/2008 1232	09/03/2007 0202
08-0000375	FF falls through hole into basement, Mayday occurs.	08/12/2008 1845	03/24/2008 1000
08-0000368	Keep safety in mind on ladders.	08/06/2008 0837	07/11/2008 2130
08-0000354	Wall and ceiling collapse threatens FF.	07/27/2008 1341	09/01/2007 1400
08-0000339	Six foot deep pit discovered in floor during overhaul.	07/14/2008 1629	07/02/2008 0345
08-0000334	Backdraft endangers search team.	07/14/2008 1259	06/13/2006 1800
08-0000333	Floor collapses in lightweight construction.	07/14/2008 0949	12/25/2007 0500
08-0000324	FF breathes in smoke due to faulty face piece.	07/13/2008 2218	02/09/2003 1300
08-0000297	Chief officer has seizure on incident.	06/15/2008 2224	07/15/1995 1600
08-0000287	Changing conditions in ballon-frame home.	06/07/2008 0006	05/13/2008 1206
08-0000285	Captain escapes injury from chain saw.	06/04/2008 2116	06/03/2008 0000
08-0000277	Roof and truss system collapses on firefighters.	05/28/2008 2247	05/28/2008 0906
08-0000274	Firefighter thrown from rear of pumper during layout.	05/25/2008 1102	04/15/2008 0300
08-0000273	PPE saves firefighter from serious injury.	05/23/2008 1449	05/19/2008 0615
08-0000272	Hoseline operation blows fire on crew.	05/22/2008 2151	05/06/2006 0200
08-0000267	Firefighter falls over railing.	05/21/2008 2311	07/12/2007 0630
08-0000262	Communications place FFs in jeopardy.	05/21/2008 1433	02/05/1993 1000
08-0000260	Post-fire building collapse traps captain.	05/21/2008 1316	06/05/2004 1800
08-0000226	FF forgets to put on hood	05/07/2008 1120	04/26/2008 1800
08-0000102	Crew bails out 2nd floor window as flashover occurs.	02/21/2008 1735	02/03/2008 0200
08-0000092	Unclear mission, fogged glasses, lead to fall through floor and "Mayday."	02/17/2008 0022	02/11/2008 0930
08-0000015	FFs become disoriented in house fire	01/09/2008 1711	01/03/2008 1920
08-0000009	Supply line dragged injuring Firefighters	01/03/2008 2134	01/03/2008 0550
07-0001166	FF becomes entangled in wires	12/13/2007 1726	10/15/2005 0345
Report Number	Report	Report Date	Event Date

07-0001156	Ground power box ignites grass	12/08/2007 2214	12/08/2007 1954
07-0001102	Ground wire energizes plumbing.	10/26/2007 1302	10/24/2007 1715
07-0001098	FF walks under DO NOT ENTER banner tape	10/20/2007 1105	10/13/2007 1130
07-0001063	Aerial ladder extended as lightning rod.	09/21/2007 0834	09/03/2007 1740
07-0001032	Firefighters retreat just before smoke explosion	08/28/2007 1227	06/04/2007 0700
07-0001029	Roof slate cuts handline during fire attack	08/25/2007 1454	08/24/2007 1400
07-0001010	Improper overhaul leads to re-kindle.	08/03/2007 2217	06/09/2006 1400
07-0000942	FF falls through floor.	06/05/2007 1558	03/23/2007 1158
07-0000926	Roof collapse almost crushes FFs.	05/25/2007 0831	05/20/2007 0028
07-0000890	RIT Team activated for missing FF's	05/01/2007 0255	04/28/2007 0115
07-0000889	FF's caught in collapse of boathouse.	04/28/2007 1154	06/18/2006 1400
07-0000879	FF falls through floor during overhaul at vacant structure fire.	04/22/2007 0707	04/20/2007 2100
07-0000867	Firefighter falls through stairs.	04/16/2007 0844	04/15/2007 2343
07-0000864	Lack of situational awareness and training results in injuries at structure fire.	04/13/2007 1044	07/21/2003 0153
07-0000861	Opposing hoselines potentially injure FF's	04/12/2007 1045	11/20/2005 1300
07-0000852	No banister found in house-under-construction fire.	04/06/2007 1210	04/03/2007 0356
07-0000845	Firefighters become disoriented requiring assistance.	04/04/2007 1042	01/11/2007 0311
07-0000841	Freelancing at structure fire causes multiple hazards.	03/30/2007 1141	10/10/2005 0000
07-0000789	FF falls through burnt floor.	03/10/2007 1513	03/07/2007 1800
07-0000786	Firefighter walks over arcing electrical wire.	03/09/2007 1447	04/12/2006 1000
07-0000764	Fireground communication problems noted.	03/02/2007 1642	05/15/2006 1415
07-0000739	Lack of communication leads to potential problems at structure fire.	02/23/2007 2255	08/09/2006 0430
07-0000737	Interior operations contribute to near-miss.	02/21/2007 1125	02/19/2007 0245
07-0000736	FF becomes disoriented in house fire	02/20/2007 2136	07/16/2006 0100
07-0000731	FFs fall through tile / truss roof at attic fire.	02/17/2007 1040	07/01/1989 1300
07-0000730	FF falls through burnt 2nd story floor.	02/16/2007 0713	02/09/2007 1320
07-0000727	Turnout coats exposed to heat before entry.	02/14/2007 1156	01/11/2007 0948
07-0000723	Situational awareness at structure fire averts disaster.	02/09/2007 0707	02/08/2007 0130
07-0000715	Soffitt crashes to ground almost striking retired firefighter	02/01/2007 1430	01/30/2007 0545
07-0000713	Propane tanks explode during fire attack.	01/31/2007 0920	12/29/2006 1700
07-0000709	Firefighter descends ladder and falls into swimming pool.	01/27/2007 1408	05/15/1999 2200
07-0000698	Firefighter falls through floor into fire	01/24/2007 1743	01/23/2007 1430
07-0000696	FFs neglect to notify IC when they are trapped after ceiling collapse.	01/22/2007 2302	12/08/2006 0000
07-0000694	Lack of situational awareness results in FF's leg going through floor.	01/22/2007 1810	12/29/2006 0146
07-0000647	Loss of situational awareness causes FF to fall through floor at structure fire	01/05/2007 1522	02/10/2003 2230
Report Number	Report	Report Date	Event Date

07-0000628	Lessons learned from LODD earlier in the day pay off when floor collapses.	01/02/2007 1353	03/21/2003 2200
06-0000591	Downed power line still hot.	11/30/2006 2103	11/22/2006 0900
06-0000450	Tactical radio channel confusion	08/31/2006 0053	08/30/2006 1715
06-0000332	Pump operator narrowly misses getting hit by drunk driver.	06/20/2006 2131	07/01/2004 2200
05-0000298	Firefighter steps on a live wire during house fire.	06/10/2005 1055	04/05/2005 0733
05-0000290	Oxygen cylinders explode as crew enters structure.	06/05/2005 1300	04/10/2005 0142